


REQUEST FOR ISSUE OF SCHOOL BUILDING SAFETY CERTIFICATE-REG

1. Ref your letter No 25112/KVB/2021-22/138 dt 24 Sep 2021.
2. The detls of insp carried out by AGE B/R of GE (Central) is att as appx.
3. This for your info and further necessary action pl.



(T Shekar)
Lt Col
Garrison Engineer (C)

Encis : (As above)

Copy to :-

AGE B/R - I (C) Kolkata - For info wrt your letter No 230/BMC/94/E2 dt 26 Oct 2021.

1. The fwg has been noted during visual inspection :-

- (a) Minor cracks on wall at certain places.
- (b) Concrete hand rail on parapet found damaged at one place.
- (c) Seepage observed at three places which may be occurred through rain water pipe and roof slab junction.
- (d) Crack observed on rendering over water proofing treatment.
- (e) Some vegetation grown at roof slab and rain water pipe junction
- (f) Boundary wall is heavily damaged at places.

2. Our justification/comments on above mentioned points are as under:-

- (a) Points mentioned in para 2 (a), 2 (b) and 2 (e) are not given any negative impact on building. Hence, recommended to be rectified under regular maintenance to be done KV Ballygunge itself.
- (b) Point mentioned in Para 2 (c) and 2 (d) are pertains to roof treatment. As roof treatment work was carried by MES through CA No CWE/Kol/E-29/29 of 2018-19 hence the defects should be rectified by contractor under defect liability period of roof treatment
- (c) As the work for special repair of boundary wall of Kendriya Vidhalya Ballygunge was already sanctioned and construction agency choosed by KV Sangathan is MES. Tender for this work is under progress. Hence, points should be rectified once contract concluded.

3. In view of above our recommendation are as under :-

- (a) As there is no structural distress noticed during visual inspection by undersigned school building safety certificate may be issued by your end subject to visual inspection by GE.
- (b) As School building is more than 25 years old and keeping in view of condition of defence infrastructure in Ballygunge Maidan Camp, it is recommended to advise KV Sangathan for approach IIT/NIT/Institute of National Importance/Govt University for detailed structural audit of building.